

1. Run the right motor at full speed while the bump switch is pressed.
 - a. End the program.
2. Run the left and right motor at half speed while the limit switch is pressed.
 - a. End the program.
3. Turn on the flashlight at full brightness while the bump switch is pressed.
 - a. End the program.
4. Turn on the LED and the flashlight while the bump switch is pressed.
 - a. End the program.
5. Flash the LED on and off while the limit switch is pressed.
 - a. End the program.
6. Run the left motor for two (2) seconds then stop while the limit switch is pressed.
 - a. End the program.